HEALTHCARE
Imaging >
Global Support Operations

Field Service Bulletin No. 10

Order No.: DD+DIS223.02E

1 piece VE73C MA1

ADC Compact Plus
Type 5146/100

Centricity CR MP3510
Type 5146/200

Rating			When?		
safety relevant	reliability	new function	immediately	next service	as required
	X				**X**

Please file this document in chapter 10 of your technical documentation

Problem of Sharp White or Black Lines in Fast Scan Direction

printed in Germany 08 / 2002

AGFA

Problem

Sporadically sharp white and black lines may occur in fast scan direction.
See image for explanation.



Reason

BOL PCB within the optic module (CM+9.5146.2750.0) is considered to cause this problem.

Solution

- Contact HE/IMG-GSO
- To prevent from unjustified exchange of optic modules in the field and due to the high costs HE/IMG-GSO will validate every order after artifact image and info counter analysis.
- Place an order in the EVS-System.
- The defective spare parts must be sent back immediately to the address mentioned below as MA4 parts:

  LOG-T Retouren Stelle
  Tegernseer Landstrasse 161
  81539 München

- Spare parts are free of charge for the NSO´s